

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : BIÑAN	MONTH : JULY	YEAR : 2017
DOH ACCREDITATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-BIN

NO	SAMPLE LOCATION		DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
	ADDRESS	TYPE		***Res. Chlorine ¹	Color ²	Turbidity ³	pH ⁴	Taste/Odor ⁵	HPC ⁶	Coliforms/100 mL ⁷	
				mg/L	ACU	NTU			CFU/mL	TOTAL	<i>Escherichia coli</i>
BRGY. BIÑAN											
1	Laguna Well Field 1	S	27-Jul	1.45	-	< 0.02	7.46	-	-	ABSENCE	ABSENCE
2	Pump 6, Santol St., Phase 4C, San Jose Village I	S	18-Jul	0.98	-	< 0.02	8.5	-	< 1	ABSENCE	ABSENCE
3	Guardhouse Entrance, Phase 4C, San Jose Village I	D	18-Jul	0.49	-	< 0.02	8.38	-	10	ABSENCE	ABSENCE
4	Clubhouse, Phase 3B, San Jose Village I	D	17-Jul	0.49	-	< 0.02	8.36	-		ABSENCE	ABSENCE
5	Clubhouse, Phase 5, San Jose Village II	D	25-Jul	0.52	-	< 0.02	8.3	-	-	ABSENCE	ABSENCE
6	Pump 7, San Jose Village III	S	27-Jul	0.62	-	< 0.02	7.62	-	-	ABSENCE	ABSENCE
7	Clubhouse, Phase 6, San Jose Village III	D	27-Jul	0.66	-	< 0.02	7.78	-	-	ABSENCE	ABSENCE
BRGY. CANLALAY											
8	#132 A. Bonifacio St.	D	26-Jul	< 0.20	-	0.38	7.45	-	130	ABSENCE	ABSENCE
9	Golden City Canlalay Clubhouse	D	26-Jul	0.84	-	< 0.02	6.85	-	7	ABSENCE	ABSENCE
10	Canlalay Elementary School	D	26-Jul	7.3	-	0.22	7.3	-	-	ABSENCE	ABSENCE
BRGY. DELA PAZ											
11	Almeda	S	26-Jul	7.56	-	< 0.02	7.56	-	-	ABSENCE	ABSENCE
12	Drinking Fountain, Dela Paz Elementary School	D	4-Jul	< 0.20	-	1.04	7.32	-	-	ABSENCE	ABSENCE
13	Barangay Hall	D	26-Jul	0.69	-	0.06	7.69	-	-	ABSENCE	ABSENCE
BRGY. GANADO											
14	Drinking Fountain, Ganado Elementary School	D	17-Jul	0.66	-	< 0.02	8.18	-	< 1	ABSENCE	ABSENCE
BRGY. HALANG											
15	9999 WP Metroville Complex	S	4-Jul	1.18	< 2	< 0.02	7.10	**unobjectionable	< 1	ABSENCE	ABSENCE
16	Clubhouse, Metroville Complex	D	4-Jul	1.43	-	1.74	7.25	-	-	ABSENCE	ABSENCE
BRGY. LANGKIWA											
17	Block 3 Lot 19 Phase 2, Southville Langkiwa	D	25-Jul	0.48	-	< 0.02	7.31	-	-	ABSENCE	ABSENCE
18	Block 65 Lot 5 Phase 1, Southville Langkiwa	D	25-Jul	0.4	-	< 0.02	7.25	-	2	ABSENCE	ABSENCE
19	Block 20 Lot 7 Phase 3, Southville Langkiwa	D	25-Jul	0.52	-	< 0.02	7.17	-	1	ABSENCE	ABSENCE
20	Block 28 Lot 8 Phase 2, Southville Langkiwa	D	25-Jul	0.52	-	< 0.02	7.39	-	-	ABSENCE	ABSENCE
21	Block 18 Lot 11 Phase 4, Southville Langkiwa	D	25-Jul	0.52	-	< 0.02	7.2	-	-	ABSENCE	ABSENCE
22	Block 31 Lot 27, Phase 3, Southville Langkiwa	D	25-Jul	0.55	-	< 0.02	7.29	-	-	ABSENCE	ABSENCE

23	Drinking Fountain, Langkiwa Elementary School	D	25-Jul	0.55	-	< 0.02	7.39	-	< 1	ABSENCE	ABSENCE
BRGY. LOMA											
24	Water Pump, Celina Mansion Subdivision	S	13-Jul	0.61	-	< 0.02	-	-	-	ABSENCE	ABSENCE
25	Block 2 Lot 29, Celina Mansion Subdivision	D	13-Jul	0.66	-	< 0.02	-	-	1	ABSENCE	ABSENCE
26	Water Pump, Block 4 Lot 37, Celina Technopark	S	13-Jul	0.25	-	< 0.02	-	-	-	ABSENCE	ABSENCE
27	Block 6 Lot 58, Celina Technopark	D	13-Jul	< 0.20	-	< 0.02	-	-	330	ABSENCE	ABSENCE
28	Block 8, Laguna Bel-Air 3	S	14-Jul	0.75	-	< 0.02	7.26	-	-	ABSENCE	ABSENCE
29	Brenna Model House, Block 90 Lot 5, Laguna Bel-Air 3	D	14-Jul	0.72	-	< 0.02	7.29	-	-	ABSENCE	ABSENCE
30	Block 2, Phase 4, Laguna Bel-Air 3	S	14-Jul	0.54	-	< 0.02	7.37	-	-	ABSENCE	ABSENCE
31	Hilcrest Road, Block 2, Laguna Bel-Air 3	D	14-Jul	7.2	-	< 0.02	7.2	-	-	ABSENCE	ABSENCE
32	Block 50, Phase 2, Laguna Bel-Air 3	S	14-Jul	0.58	-	< 0.02	7.2	-	-	ABSENCE	ABSENCE
33	Clubhouse, Laguna Bel-Air 3	D	14-Jul	0.71	-	< 0.02	7.19	-	-	ABSENCE	ABSENCE
34	Drinking Fountain, Loma Elementary School	D	13-Jul	0.5	-	< 0.02	-	-	< 1	ABSENCE	ABSENCE
BRGY. MALAMIG											
35	Block 5 Lot 16	D	25-Jul	0.40	-	0.02	7.66	-	63	ABSENCE	ABSENCE
BRGY. MAMPLASAN											
36	Tank, Verdana Homes Subdivision	S	25-Jul	< 0.20	-	< 0.02	7.86	-	< 1	ABSENCE	ABSENCE
37	Clubhouse, Verdana Homes Subdivision	D	25-Jul	1.83	-		7.89	-	-	ABSENCE	ABSENCE
38	United Laboratories (UNILAB) Inc.	D	17-Jul	0.42	-	0.67	-	-	< 1	ABSENCE	ABSENCE
BRGY. POBLACION											
39	Brgy. Health Center	S	13-Jul					-	1	ABSENCE	ABSENCE
BRGY. PLATERO											
40	Drinking Fountain, St. Michael School of Biñan	D	4-Jul	0.28	-	< 0.02	8.19	-	-	ABSENCE	ABSENCE
41	Sea-oil, National Road	D	4-Jul	< 0.20	-	< 0.02	7.52	-	< 1	ABSENCE	ABSENCE
BRGY. SAN ANTONIO											
42	Biñan City Hall	S	4-Jul	0.83	-	< 0.02	7.93	-	9	ABSENCE	ABSENCE
43	Arena Sports Complex	D	4-Jul	0.93	-	< 0.02	7.57	-	-	ABSENCE	ABSENCE
44	9022 Water Pump (WP) Faraon Subdivision	S	13-Jul	1.04	< 2	< 0.02	-	**unobjectionable	-	ABSENCE	ABSENCE
45	Brgy. Heath Center, Faraon	D	18-Jul	0.92	-	< 0.02	-	-	8	ABSENCE	ABSENCE
46	Block 5 Lot 12, Margarita Homes Subdivision	D	13-Jul	< 0.20	-	0.36	-	-	-	ABSENCE	ABSENCE
47	Drinking Fountain 1, Faraon Elementary School	D	18-Jul	0.85	-	< 0.02	8.61	-	< 1	ABSENCE	ABSENCE
48	Drinking Fountain 2, Faraon Elementary School	D	18-Jul	0.88	-	< 0.02	8.55	-	< 1	ABSENCE	ABSENCE
49	Cistern Tank, Pavillion Mall	D	17-Jul	0.54	-	< 0.02	-	-	38	ABSENCE	ABSENCE
50	Jollibee, Pavillion Mall	D	17-Jul	0.49	-	< 0.02	-	-	3	ABSENCE	ABSENCE
BRGY. SANTO NIÑO											
51	Jollibee National Hi-Way	D	17-Jul	0.57	-	< 0.02	-	-	< 1	ABSENCE	ABSENCE
BRGY. SAN VICENTE											
52	407 San Vicente	S	13-Jul	0.81	-	0.03	-	-	< 1	ABSENCE	ABSENCE
53	B8 L6, Bayabas St., Olivarez 7	D	13-Jul	0.74	-	< 0.02	8.26	-	< 1	ABSENCE	ABSENCE
54	Binan Doctors Hospital	D	26-Jul		-		-	-	-	ABSENCE	ABSENCE

55	Drinking Fountain, San Vicente Elementary Sch.	D	13-Jul	0.86	-	0.39	-	-	-	ABSENCE	ABSENCE
BRGY. SANTO TOMAS											
56	Gate Entrance, Adelina Complex III Subdivision	D	25-Jul	0.54	-	< 0.02	7.44	-	< 1	ABSENCE	ABSENCE
57	Block 2 Lot 14, Phase 1B, Olivarez Homes South	D	4-Jul	0.4	-	< 0.02	7.08	-		ABSENCE	ABSENCE
59	Block 2 Lot 44, Phase 4, Olivarez Homes South	D	4-Jul	0.34	-	< 0.02	7.22	-		ABSENCE	ABSENCE
60	Pump House, Kalibo St., South City Homes	S	4-Jul	< 0.20	-	0.22	7.45	-	< 1	ABSENCE	ABSENCE
61	Block 1 Lot 5A, Bais St., Pragmatic	D	4-Jul	< 0.20	-	0.10	7.49	-	-	ABSENCE	ABSENCE
63	Block 5 Lot 2, South City Homes	D	25-Jul	0.49	-	< 0.02	7.3	-	-	ABSENCE	ABSENCE
64	Deepwell 3, Phase XI, South City Homes	S	25-Jul	0.91	-	0.06	7.52	-	< 1	ABSENCE	ABSENCE
65	Block 42 Lot 16, Phase XI, South City Homes	D	25-Jul	0.87	-	0.04	7.56	-	-	ABSENCE	ABSENCE
66	Pump, South Plains II Subdivision	S	27-Jul	0.40	-	0.49	7.40	-	-	ABSENCE	ABSENCE
67	Block 11 Lot 2, South Plains II Subdivision	D	27-Jul	0.48	-	0.26	7.48	-	-	ABSENCE	ABSENCE
68	Pump, Amsterdam St., Phase 2, Town & Country	S	4-Jul	0.35	-	0.04	7.12	-	-	ABSENCE	ABSENCE
69	Block 35 Lot 21, Town & Country	D	4-Jul	0.38	-	0.17	7.38	-	< 1	ABSENCE	ABSENCE
71	Block 2 Lot 5, Town & Country	D	4-Jul	0.59	-	0.07	7.18	-	< 1	ABSENCE	ABSENCE
BRGY. SORO - SORO											
72	9067 Soro-soro	S	4-Jul	0.85	< 2	< 0.02	7.26	*unobjectionable	< 1	ABSENCE	ABSENCE
73	#76 Soro-Soro	D	4-Jul	0.81	-	< 0.02	7.16	-	-	ABSENCE	ABSENCE
BRGY. TUBIGAN											
74	#100 Florinda Compound	D	4-Jul	0.59	-	0.04	7.94	-	-	ABSENCE	ABSENCE
BRGY. ZAPOTE											
75	Water Pump, Althea	S	4-Jul	< 0.20	-	< 0.02	7.68	-	100	ABSENCE	ABSENCE
76	Block 6 Lot 4, Althea	D	4-Jul	< 0.20	-	< 0.02	7.37	-	-	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		76	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE

REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU - Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA

Analytical Laboratory Head

PRC License No. 0012740

NOTED BY:



CYRIL A. ERICA

Laboratory Services Manager

PRC License No. 0054161

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : SANTA ROSA				MONTH : JULY				YEAR : 2017			
DOH ACCREDITATION NO : 04A-010-16-LW-2				VALIDITY : December 31, 2018				DOCUMENT NO : 17WQM-07-STR			
NO	SAMPLE LOCATION		DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
	ADDRESS	TYPE		***Res. Chlorine ¹ mg/L	Color ² ACU	Turbidity ³ NTU	pH ⁴	Taste/Odor ⁵	HPC ⁶ CFU/mL	Coliforms/100 mL ⁷ TOTAL	<i>Escherichia coli</i>
BRGY. BALIBAGO											
1	#1354 Facundo Compound	D	13-Jul	0.61	-	0.14	7.39	-	-	ABSENCE	ABSENCE
2	5555 Water Pump Elevated, South Hampton	S	14-Jul	0.75	< 2	< 0.02	8.71	*unobjectionable	-	ABSENCE	ABSENCE
3	Clubhouse, South Hampton	D	14-Jul	0.77	-	0.06	8.50	-	-	ABSENCE	ABSENCE
4	Block 5 Lot 19, JB Village, Sta. Rosa Tagaytay Road	D	14-Jul	0.88	-	< 0.02	8.28	-	-	ABSENCE	ABSENCE
5	Cistern Tank, Waltermart Sta. Rosa	D	31-Jul	0.76	-	< 0.02	7.49	-	-	ABSENCE	ABSENCE
6	Mang Inasal, Waltermart Sta. Rosa	D	31-Jul	0.68	-	< 0.02	7.81	-	-	ABSENCE	ABSENCE
BRGY. CAINGIN											
7	Block 57, Phase 1, Southville	S	6-Jul	0.48	< 2	< 0.02	7.88	**unobjectionable	-	ABSENCE	ABSENCE
8	Block 52 Lot 23, Phase 1, Southville	D	6-Jul	0.46	-	0.08	7.67	-	-	ABSENCE	ABSENCE
9	Block 46 Lot 2, Phase 2, Southville	D	6-Jul	1.11	-	0.11	7.76	-	-	ABSENCE	ABSENCE
10	Caingin Elementary School	D	6-Jul	0.44	-	< 0.02	7.81	-	-	ABSENCE	ABSENCE
BRGY. DILA											
11	Phase 3E, Mabuhay Homes 2000	S	13-Jul	< 0.20	< 2	< 0.02	7.12	**unobjectionable	170	ABSENCE	ABSENCE
12	Block 2 Lot 10, Mabuhay Homes 2000	D	13-Jul	< 0.20	-	< 0.02	7.15	-	-	ABSENCE	ABSENCE
13	Block 12, Phase 2E, Mabuhay Homes 2000	S	13-Jul	< 0.20	-	0.09	7.51	-	8	ABSENCE	ABSENCE
14	Block 13 Lot 5, Phase 2E, Mabuhay Homes 2000	D	13-Jul	< 0.20	-	0.05	7.31	-	-	ABSENCE	ABSENCE
15	Drinking Fountain, Dila Elementary School	D	17-Jul	< 0.20	-	0.45	-	-	1	ABSENCE	ABSENCE
BRGY. DITA											
16	Block 24 Lot 2, New Santa Rosa Homes	S	13-Jul	0.22	-	0.07	7.02	-	2	ABSENCE	ABSENCE
17	Block 19 Lot 11, New Santa Rosa Homes	D	13-Jul	0.59	-	0.95	7.21	-	-	ABSENCE	ABSENCE
18	Block 4 Lot 32, San Lorenzo Royale	S	6-Jul	0.25	-	0.24	7.52	-	-	ABSENCE	ABSENCE
19	Block 11 Lot 52, San Lorenzo Royale	D	6-Jul	0.2	-	0.40	7.42	-	-	ABSENCE	ABSENCE
20	Water Tank, SolCar Ville Subdivision	S	13-Jul	0.41	< 2	< 0.02	6.58	**unobjectionable	< 1	ABSENCE	ABSENCE
21	Block 3 Lot 7, SolCar Ville Subdivision	D	13-Jul	0.30	-	< 0.02	6.67	-	-	ABSENCE	ABSENCE
22	Water Tank, Villa Esmeralda	S	6-Jul	0.20	-	0.13	7.36	-	-	ABSENCE	ABSENCE
23	Alabaster St., Villa Esmeralda	D	6-Jul	0.38	-	0.89	7.26	-	-	ABSENCE	ABSENCE
24	#1780 National Road	D	17-Jul	0.52	-	0.17	-	-	26	ABSENCE	ABSENCE
25	R & B Ice Plant, Inc.	D	14-Jul	0.63	-	< 0.02	8.43	-	-	ABSENCE	ABSENCE

BRGY. DON JOSE											
26	Block 7 Lot 62, Phase 3, Laguna Bel-Air	S	12-Jul	9.2	-	< 0.02	-	-	-	ABSENCE	ABSENCE
27	Science HighSchool, Phase 1, Laguna Bel-Air	D	12-Jul	0.82	-	< 0.02	-	-	-	ABSENCE	ABSENCE
28	Block 34 Lot 14, Phase 1, Laguna Bel-Air	S	12-Jul	0.61	-	< 0.02	-	-	-	ABSENCE	ABSENCE
29	Block 34 Lot 59, Phase 1, Laguna Bel-Air	D	12-Jul	1.32	-	< 0.02	-	-	-	ABSENCE	ABSENCE
30	Clubhouse, Block 62, Laguna Bel-Air	D	12-Jul	0.85	-	< 0.02	-	-	-	ABSENCE	ABSENCE
31	Water Pump, Block 71, Phase 4, Laguna Bel-Air	S	12-Jul	0.98	-	< 0.02	-	-	-	ABSENCE	ABSENCE
32	Block 71 Lot 4, Phase 2, Laguna Bel-Air	D	12-Jul	0.93	-	< 0.02	-	-	-	ABSENCE	ABSENCE
33	Block 108, Phase 2, Laguna Bel-Air	S	12-Jul	0.85	-	< 0.02	-	-	-	ABSENCE	ABSENCE
34	Church, Block 108, Phase 2, Laguna Bel-Air	D	12-Jul	0.82	-	0.3	-	-	-	ABSENCE	ABSENCE
35	Block 43, Laguna Bel-Air IV	S	12-Jul	0.9	-	< 0.02	-	-	-	ABSENCE	ABSENCE
36	Block 47 Lot 22 Laguna Bel-Air IV	D	12-Jul	0.90	-	< 0.02	-	-	-	ABSENCE	ABSENCE
37	8001, Pump 1, Acacia St., Santa Rosa Village I	S	19-Jul	0.55	-	< 0.02	-	-	-	ABSENCE	ABSENCE
38	Clubhouse., Santa Rosa Village I	D	14-Jul	0.21	-	0.04	8.43	-	-	ABSENCE	ABSENCE
39	Pump 9 & 10, Rembrandt St., Santa Rosa Estates I	S	18-Jul	0.6	-	< 0.02	8.16	-	-	ABSENCE	ABSENCE
40	Reservoir, Hacienda Sta. Elena	D	27-Jul	0.42	-	< 0.02	7.54	-	1	ABSENCE	ABSENCE
BRGY. KANLURAN											
41	#621 Rizal Boulevard	D	24-Jul	< 0.20	-	< 0.02	6.82	-	< 1	ABSENCE	ABSENCE
BRGY. LABAS											
42	Source, Alfonso Homes I	S	26-Jul	0.41	< 2	< 0.02	7.58	**unobjectionable	-	ABSENCE	abSENCE
43	Block 18 Lot 2, Alfonso Homes I	D	26-Jul	0.36	-	< 0.02	7.37	-	-	ABSENCE	ABSENCE
BRGY. MACABLING											
44	Deepwell, Buena Rosa 9 Subdivision	S	26-Jul	1.13	< 2	< 0.02	7.62	**unobjectionable	9	ABSENCE	ABSENCE
45	Block 5 Lot 2, Phase 2, Buena Rosa 9 Subdivision	D	26-Jul	0.98	-	< 0.02	7.63	-	-	ABSENCE	ABSENCE
46	Deepwell, Corinthian Subdivision	S	27-Jul	2.18	< 2	< 0.02	7.08	*unobjectionable	< 1	ABSENCE	ABSENCE
47	Guardhouse Entrance, Corinthian Subdivision	D	27-Jul	2.11	-	< 0.02	7.54	-	< 1	ABSENCE	ABSENCE
48	Deepwell, Rosemont Subdivision	S	26-Jul	1.86	< 2	< 0.02	7.83	**unobjectionable	< 1	ABSENCE	ABSENCE
49	Block 1 Lot 16, Rosemont Subdivision	D	26-Jul	1.81	-	< 0.02	7.22	-	-	ABSENCE	ABSENCE
50	Water Pump, Metrogate	S	26-Jul	0.68	< 2	< 0.02	7.78	**unobjectionable	1	ABSENCE	ABSENCE
51	Clubhouse, Metrogate	D	26-Jul	0.67	-	< 0.02	7.99	-	-	ABSENCE	ABSENCE
BRGY. MALITLIT											
52	Water Pump, Casan Residencia Subdivision	S	17-Jul	0.32	-	0.05	-	-	< 1	ABSENCE	ABSENCE
53	Block 1 Lot 1, Casan Residencia Subdivision	D	17-Jul	0.32	-	0.15	-	-	58	ABSENCE	ABSENCE
54	Block 3 Lot 1, Phase 1A Annex, San Lorenzo Subd.	S	12-Jul	0.69	< 2	< 0.02	7.07	**unobjectionable	-	ABSENCE	ABSENCE
55	Block 5 Lot 25, Phase 1A Annex, San Lorenzo Subd.	D	6-Jul	0.60	-	< 0.02	6.98	-	-	ABSENCE	ABSENCE
56	Main Road, Phase 2, Terra Fortuna	S	6-Jul	0.46	-	0.27	7.22	-	-	ABSENCE	ABSENCE
57	Clubhouse, Terra Fortuna	D	6-Jul	0.41	-	0.27	7.36	-	-	ABSENCE	ABSENCE
58	9999 W, Villa Las Casas	S	6-Jul	< 0.20	-	< 0.02	6.89	-	-	ABSENCE	ABSENCE
59	Block 1 Lot 17, Villa Las Casas	D	6-Jul	< 0.20	-	< 0.02	6.92	-	-	ABSENCE	ABSENCE
60	Malitlit Elementary School	D	20-Jul	0.45	-	< 0.02	7.37	-	-	ABSENCE	ABSENCE
BRGY. MALUSAK											
61	Drinking Fountain 1, Central 1 Elementary Sch.	D	24-Jul	0.83	-	0.06	7.57	-	2	ABSENCE	ABSENCE

62	Drinking Fountain 2, Central 1 Elementary Sch.	D	24-Jul	0.89	-	0.02	7.59	-	< 1	ABSENCE	ABSENCE
63	Drinking Fountain 3, Central 1 Elementary Sch.	D	24-Jul	1.06	-	0.08	7.60	-	< 1	ABSENCE	ABSENCE
BRGY. MARKET AREA											
64	Source, Market Area	S	24-Jul	1.36	< 2	< 0.02	7.1	**unobjectionable	< 1	ABSENCE	ABSENCE
65	Block 9 Lot 2, Terry Town West	D	24-Jul	1.19	-	< 0.02	6.86	-	< 1	ABSENCE	ABSENCE
BRGY. POOC											
66	Deepwell, Alinsod	S	13-Jul	0.74	< 2	< 0.02	7.6	**unobjectionable	< 1	ABSENCE	ABSENCE
67	Tank, Villa Mercedes	S	17-Jul	< 0.20	< 2	< 0.02	-	**unobjectionable	< 1	ABSENCE	ABSENCE
68	Block 5 Lot 25, Villa Mercedes	D	17-Jul	< 0.20	-	< 0.02	-	-	< 1	ABSENCE	ABSENCE
BRGY. PULONG SANTA CRUZ											
69	Water Pump, Pulong Sta. Cruz	S	14-Jul	1.15	< 2	< 0.02	8.24	**unobjectionable	-	ABSENCE	ABSENCE
70	Block 7 Lot 3 Mercado Village, Pulong Sta. Cruz	D	14-Jul	1.06	-	< 0.02	8.53	-	-	ABSENCE	ABSENCE
71	Block 6 Lot 8, Buklod Diwa	D	28-Jul	1.15	-	< 0.02	-	-	-	ABSENCE	ABSENCE
BRGY. SINALHAN											
72	Block 5 Lot 7, Phase 1, Bayshore I	D	13-Jul	< 0.20	< 2	< 0.02	7.66	*unobjectionable	76	ABSENCE	ABSENCE
73	Block 6 Lot 10, Bayshore II	D	13-Jul	< 0.20	-	0.38	7.57	-	-	ABSENCE	ABSENCE
74	4026, Sinalhan Road, Purok 2	S	13-Jul	0.65	< 2	0.04	7.49	*unobjectionable	< 1	ABSENCE	ABSENCE
75	Amoranto Compound, Phase 2, Sinalhan	D	13-Jul	0.59	-	0.42	7.48	-	-	ABSENCE	ABSENCE
BRGY. SANTO DOMINGO											
76	Clubhouse Santa Rosa Estates II	D	27-Jul	0.72	-	< 0.02	7.99	-	-	ABSENCE	ABSENCE
BRGY. TAGAPO											
77	Water Pump, Fairfield of Margana Subdivision	S	24-Jul	< 0.20	-	< 0.02	7.5	-	< 1	ABSENCE	ABSENCE
78	Block 7 Lot 5, Fairfield of Margana Subdivision	D	24-Jul	< 0.20	-	< 0.02	7.44	-	27	ABSENCE	ABSENCE
79	Water Pump, Rosewood Homes I	S	24-Jul	0.74	< 2	< 0.02	7.68	*unobjectionable	< 1	ABSENCE	ABSENCE
80	Block 3 Lot 31, Rosewood Homes I	D	24-Jul	0.38	-	< 0.02	7.71	-	< 1	ABSENCE	ABSENCE
81	Block 17 Lot 19, Rosewood Homes II	D	24-Jul	0.7	-	< 0.02	7.68	-	< 1	ABSENCE	ABSENCE
82	#31 JP Rizal Boulevard	D	24-Jul	0.61	-	< 0.02	7.67	-	< 1	ABSENCE	ABSENCE
83	Water Pump, Buena Rosa 1 Subdivision	S	26-Jul	1.49	-	< 0.02	7.87	-	< 1	ABSENCE	ABSENCE
84	Block 3 Lot 1, Buena Rosa 1 Subdivision	D	26-Jul	0.38	-	< 0.02	7.96	-	-	ABSENCE	ABSENCE
85	Block 1 Lot 64, Buena Rosa 10 Subdivision	D	24-Jul	0.41	-	0.03	7.62	-	< 1	ABSENCE	ABSENCE
86	Cistern Tank, SM Sta. Rosa	D	20-Jul	0.93	-	< 0.02	7.93	-	-	ABSENCE	ABSENCE
87	Admin. Pantry, SM Sta. Rosa	D	20-Jul	1.05	-	< 0.02	7.87	-	-	ABSENCE	ABSENCE
88	Cistern Tank, Robinson's Mall	D	20-Jul	1.10	-	0.15	8.00	-	-	ABSENCE	ABSENCE
89	Chummie Shawarma, Robinson's Mall	D	20-Jul	1.06	-	0.15	7.97	-	-	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		89	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU - Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA
Analytical Laboratory Head
PRC License No. 0012740

NOTED BY:



CYRIL A. ERICA
Laboratory Services Manager
PRC License No. 0054161

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : CABUYAO	MONTH : JULY	YEAR : 2017
DOH ACCREDITATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-CAB

NO	SAMPLE LOCATION		DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
	ADDRESS	TYPE		***Res. Chlorine ¹	Color ²	Turbidity ³	pH ⁴	Taste/Odor ⁵	HPC ⁶	Coliforms/100 mL ⁷	
				mg/L	ACU	NTU			CFU/mL	TOTAL	<i>Escherichia coli</i>
BRGY. BANAY-BANAY											
1	Water Pump, Block 63, Lakeside Nest Subdivision	S	18-Jul	1.71	< 2	< 0.02	7.75	**unobjectionable	-	ABSENCE	ABSENCE
2	Block 10 Lot 5, Lakeside Nest Subdivision	D	18-Jul	1.01	-	< 0.02	7.78	-	< 1	ABSENCE	ABSENCE
BRGY. BANLIC											
3	Water Pump, Gran Seville Subdivision	S	20-Jul	0.19	-	< 0.02	6.88	-	-	ABSENCE	ABSENCE
4	Guardhouse, Gran Seville Subdivision	D	20-Jul	0.32	-	< 0.02	7.52	-	-	ABSENCE	ABSENCE
BRGY. BIGAA											
5	#253 Elsol Subdivision	D	20-Jul	0.29	-	< 0.02	8.06	-	-	ABSENCE	ABSENCE
BRGY. GULOD											
6	Block 12, Noah St., Celestine Ville	S	18-Jul	1.64	< 2	0.18	7.87	**unobjectionable	-	ABSENCE	ABSENCE
7	Block 1 Lot 12, Celestine Ville	D	18-Jul	0.94	-	0.02	7.76	-	< 1	ABSENCE	ABSENCE
BRGY. MAMATID											
8	Tank, Buena Rosario Subdivision	S	18-Jul	0.49	-	0.06	7.56	-	-	ABSENCE	ABSENCE
9	Block 7 Lot 6, Buena Rosario Subdivision	D	18-Jul	0.28	-	0.11	7.73	-	4	ABSENCE	ABSENCE
10	Block 101 Samar st., Phase 1, Mabuhay City	S	18-Jul	0.5	< 2	< 0.02	7.85	**unobjectionable	-	ABSENCE	ABSENCE
11	Block 95 Lot 57, Guimaras St., Phase 1, Mabuhay City	D	18-Jul	0.44	-	< 0.02	7.81	-	11	ABSENCE	ABSENCE
12	Block 141, Carmona St., Phase 2, Mabuhay City	S	18-Jul	0.58	< 2	< 0.02	7.89	**unobjectionable	-	ABSENCE	ABSENCE
13	Block 134 Lot 22, Phase 2, Mabuhay City	D	18-Jul	0.57	-	< 0.02	7.89	-	2	ABSENCE	ABSENCE
14	Block 198, Galacia St., Phase 2, Mabuhay City	S	18-Jul	0.41	< 2	< 0.02	7.04	**unobjectionable	-	ABSENCE	ABSENCE
15	Block 222 Lot 20, Mabuhay Ave, Phase 2, Mabuhay	D	18-Jul	0.38	-	< 0.02	7.78	-	< 1	ABSENCE	ABSENCE
16	Panganig St., Phase 3 Cluster, Mabuhay City	S	25-Jul	0.5	< 2	< 0.02	6.85	**unobjectionable	-	ABSENCE	ABSENCE
17	Block 1 Lot 7 Dizon St., Phase 3 Cluster, Mabuhay	D	25-Jul	0.66	-	< 0.02	7.50	-	< 1	ABSENCE	ABSENCE
18	Block 22 Lot 70, Phase 3 Luxury, Mabuhay City	S	25-Jul	0.59	< 2	< 0.02	7.76	**unobjectionable	-	ABSENCE	ABSENCE
19	Block 19 Lot 13, Malang St., Phase 3 Luxury,	D	25-Jul	0.46	-	< 0.02	7.99	-	< 1	ABSENCE	ABSENCE
20	Joshua St., Phase 5, Mabuhay City	S	19-Jul	0.5	< 2	< 0.02	8.28	**unobjectionable	-	ABSENCE	ABSENCE
21	Block 31 Lot 134, Joshua St., Phase 5, Mabuhay City	D	19-Jul	0.46	-	< 0.02	-	-	2	ABSENCE	ABSENCE
22	Source, Phase 1E Mabuhay Executive	S	18-Jul	0.75	< 2	< 0.02	7.82	*unobjectionable	-	ABSENCE	ABSENCE

23	Block 239 Lot 3, Phase 1E Mabuhay Executive	D	18-Jul	0.56	-	< 0.02	7.87	-	14	ABSENCE	ABSENCE
BRGY. MARINIG											
24	Block 3 Lot 17, Phase 1, Celestine Homes	S	19-Jul	0.93	< 2	< 0.02	7.86	**unobjectionable	< 1	ABSENCE	ABSENCE
25	Block 23, Lot 10, Phase 1, Celestine Homes	D	19-Jul	0.89	-	< 0.02	7.89	-	-	ABSENCE	ABSENCE
26	Block 9, Carnation St., Phase 2, Celestine Homes	S	28-Jul	0.97	< 2	< 0.02	-	**unobjectionable	-	ABSENCE	ABSENCE
27	Block 11 Lot 19, Phase 2, Celestine Homes	D	28-Jul	86	-	< 0.02	-	-	-	ABSENCE	ABSENCE
28	Block 25, Phase 3, Southville	S	20-Jul	0.55	< 2	< 0.02	7.78	**unobjectionable	-	ABSENCE	ABSENCE
29	Block 19 Lot 33, Phase 3, Southville	D	20-Jul	0.93	-	0.41	7.68	-	-	ABSENCE	ABSENCE
BRGY. NIUGAN											
30	Block 2 Lot 6, St. Francis Homes 6	D	25-Jul	0.2	-	< 0.02	7.84	-	32	ABSENCE	ABSENCE
31	Block 45, Phase 8, Southville	S	20-Jul	0.6	< 2	< 0.02	7.94	**unobjectionable	-	ABSENCE	ABSENCE
32	Block 40 Lot 132, Southville	D	25-Jul	0.39	-	< 0.02	7.93	-	-	ABSENCE	ABSENCE
33	Block 54, Phase 10, Southville	S	20-Jul	0.45	< 2	0.54	7.45	**unobjectionable	-	ABSENCE	ABSENCE
34	Block 47 Lot 101, Phase 10, Southville	D	20-Jul	0.06	-	< 0.02	7.51	-	-	ABSENCE	ABSENCE
BRGY. PULO											
35	Water Pump, Block 12 Lot 22, Cabuyao Central	S	25-Jul	0.25	-	< 0.02	8.11	-	-	ABSENCE	ABSENCE
36	Clubhouse, Narra Avenue, Cabuyao Central	D	19-Jul	0.35	-	0.16	-	-	< 1	ABSENCE	ABSENCE
37	Water Pump, Block 11, Willow Park Homes	S	19-Jul	0.32	< 2	< 0.02	8.43	**unobjectionable	-	ABSENCE	ABSENCE
38	Clubhouse, Willow Park Homes	D	19-Jul	0.26	-	< 0.02	8.47	-	4	ABSENCE	ABSENCE
BRGY. SALA											
39	Guardhouse, Main St., Multiland III	D	19-Jul	0.39	-	0.19	7.83	-	-	ABSENCE	ABSENCE
BRGY. SAN ISIDRO											
40	Source, Multiland IV	S	20-Jul	< 0.20	-	0.07	7.33	-	-	ABSENCE	ABSENCE
41	Block 3 Lot 33, Multiland IV	D	19-Jul	0.03	-	< 0.02	-	-	-	ABSENCE	ABSENCE
42	Water Pump, San Isidro Heights Subdivision	S	19-Jul	0.51	-	0.26	-	-	-	ABSENCE	ABSENCE
43	Block 3 Lot 1, San Isidro Heights Subdivision	D	19-Jul	0.377	-	< 0.02	-	-	1	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		43	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU - Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA
Analytical Laboratory Head
PRC License No. 0012740

NOTED BY:



CYBIL A. ERICA
Laboratory Services Manager
PRC License No. 0054161

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES

SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : CALAMBA	MONTH : JULY	YEAR : 2017
DOH ACCREDIATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-CAL

NO	SAMPLE LOCATION		DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
	ADDRESS	TYPE		***Res. Chlorine ¹	Color ²	Turbidity ³	pH ⁴	Taste/Odor ⁵	HPC ⁶	Coliforms/100 mL ⁷	
				mg/L	ACU	NTU			CFU/mL	TOTAL	<i>Escherichia coli</i>
BRGY. BARANDAL											
1	Deepwell 1, Amaia Scapes Calamba	S	19-Jul	0.79	-	< 0.02	7.71	-	-	ABSENCE	ABSENCE
2	Block 1 Lot 2, Amaia Scapes Calamba	D	19-Jul	0.64	-	< 0.02	7.68	-	< 1	ABSENCE	ABSENCE
3	Deepwell 2, Amaia Scapes Calamba	S	19-Jul	0.49	-	< 0.02	7.65	-	-	ABSENCE	ABSENCE
4	Block 39 Lot 5, Amaia Scapes Calamba	D	19-Jul	0.49	-	< 0.02	7.86	-	11	ABSENCE	ABSENCE
BRGY. PUTING LUPA											
5	Phase 1, Greenfields	D	19-Jul	0.81	-	< 0.02	7.75	-	-	ABSENCE	ABSENCE
6	Block 11, Kanlaon St., Greenfields	D	19-Jul	0.82	-	< 0.02	7.71	-	-	ABSENCE	ABSENCE
7	Clubhouse, Greenfields	D	19-Jul	0.49	-	< 0.02	7.64	-	-	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		7	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU -Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA
Analytical Laboratory Head
PRC License No. 0012740

NOTED BY:



CYRIL A. ERICA
Laboratory Services Manager
PRC License No. 0054161



LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : ALAMINOS	MONTH : JULY	YEAR : 2017
DOH ACCREDIATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-ALA

SAMPLE LOCATION			DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
NO	ADDRESS	TYPE		***Res. Chlorine ¹ mg/L	Color ² ACU	Turbidity ³ NTU	pH ⁴	Taste/Odor ⁵	HPC ⁶ CFU/mL	Coliforms/100 mL ⁷	
									TOTAL	Escherichia coli	
BRGY. SAN ANDRES											
1	Water Tank, Bellavita Homes	S	26-Jul	0.27	< 2	0.08	7.63	**unobjectionable	-	ABSENCE	ABSENCE
2	Block 8 Lot 1, Phase 1, BellaVita Homes	D	26-Jul	0.28	-	< 0.02	7.27	-	6	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		2	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU -Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution


DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:


JOVEN M. MARAVILLA
 Analytical Laboratory Head
 PRC License No. 0012740

NOTED BY:


CYRIL A. ERICA
 Laboratory Services Manager
 PRC License No. 0054161

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : SANTA CRUZ	MONTH : JULY	YEAR : 2017
DOH ACCREDIATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-STC

SAMPLE LOCATION			DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
NO	ADDRESS	TYPE		***Res. Chlorine ¹ mg/L	Color ² ACU	Turbidity ³ NTU	pH ⁴	Taste/Odor ⁵	HPC ⁶ CFU/mL	Coliforms/100 mL ⁷	
									TOTAL	Escherichia coli	
BRGY. BUBUKAL											
1	Source after Filter, Laguna Sports Complex	S	3-Jul	0.98	< 2	< 0.02	-	*unobjectionable	< 1	ABSENCE	ABSENCE
2	Canteen No. 4 in front of Laguna University	D	3-Jul	0.85	-	< 0.02	-	-	-	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		2	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU -Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA
Analytical Laboratory Head
PRC License No. 0012740

NOTED BY:



CYRIL A. ERICA
Laboratory Services Manager
PRC License No. 0054161

LAGUNA AAAWATER CORPORATION
OPERATIONS DEPARTMENT
LABORATORY SERVICES
SAMPLES FROM SOURCE AND CONSUMER'S TAPS - PROVINCE OF LAGUNA

CITY/MUNICIPALITY : PAGSANJAN	MONTH : JULY	YEAR : 2017
DOH ACCREDITATION NO : 04A-010-16-LW-2	VALIDITY : December 31, 2018	DOCUMENT NO : 17WQM-07-PAG

SAMPLE LOCATION			DATE COLLECTED	PHYSICAL/CHEMICAL QUALITY					MICROBIOLOGICAL QUALITY		
NO	ADDRESS	TYPE		***Res. Chlorine ¹ mg/L	Color ² ACU	Turbidity ³ NTU	pH ⁴	Taste/Odor ⁵	HPC ⁶ CFU/mL	Coliforms/100 mL ⁷	
									TOTAL	<i>Escherichia coli</i>	
BRGY. SABANG											
1	Purok 6, Moresco Ville 2	S	3-Jul	< 0.20	< 2	< 0.02	-	**unobjectionable	18	ABSENCE	ABSENCE
2	Reservoir, Moresco Ville 2	S	3-Jul	< 0.20	-	< 0.02	-	-	5	ABSENCE	ABSENCE
TOTAL SAMPLES ANALYZED		2	PNSDW LIMIT	0.30 - 1.50	10 (max)	5 (max)	6.5 - 8.5	unobjectionable	<500	ABSENCE	ABSENCE


REMARKS: Samples analyzed as submitted

LEGEND: ACU - Apparent Color Unit, NTU -Nephelometric Turbidity Unit, HPC - Heterotrophic Plate Count, ***-onsite testing, * - unobjectionable - slightly chlorinous, ** - unobjectionable - chlorinous, S - Source, D - Distribution

DETECTION LIMIT: Residual Chlorine = 0.20 mg/L, Color = 2.5 ACU, Turbidity = 0.02 NTU

METHODS USED: ¹DPD Colorimetric, ²Visual Comparison-Platinum/Cobalt, ³Nephelometric, ⁴Electrometric, ⁵Sensory, ⁶Pour Plate, ⁷Enzyme Substrate (Colilert®-18)

CERTIFIED CORRECT:



JOVEN M. MARAVILLA
 Analytical Laboratory Head
 PRC License No. 0012740

NOTED BY:



CYRIL A. ERICA
 Laboratory Services Manager
 PRC License No. 0054161